CERTIFICATION: UL DRY

NO. 62326



INSTALLATION INSTRUCTIONS

IMPORTANT

Before assembling your ACCESS LIGHTING fixture, please make sure that you carefully read through these instruction sheets. Consider having your fixture installed by a qualified licensed electrician.


NOTE: The important safeguards and instructions that appear in this manual are not meant to cover all possible conditions and situations that may occur. It must be understood that common sense, caution and care, are factors that can't be built into any product. These factors must be supplied by the person(s) caring for and operating the fixture.


GENERAL INFORMATION

All electrical connections must be in accordance with all ordinances, Local and National Electrical Codes. These fixtures are intended for mounting to a standard $4" \times 2 \ 1/2"$ metal octagon outlet box. The box must be directly supported by the building structure and U.L. Recognized.

STEP BY STEP INSTRUCTIONS

Before starting your installation disconnect the Power by turning off the Circuit Breaker or by removing the fuse at the fuse box. Just turning the light off at the light switch is not sufficient to prevent electrical shock.





OPULANCE

APPLICATION

MODEL NO.

Pendant

62326

WHAT WE PROVIDE

- Crossbar
- Mounting Hardware
- 10 x Glass shades
- 10 x 40W G9 Bulbs

WHAT YOU NEED

- Screwdriver
- Wire Cutters
- Wiring Supplies as Specified
 by Electrical Code




If there is an existing fixture remove it.

Screw all the arms into the threaded holes in the center balls and secure with allen screws.

1

CERTIFICATION: UL DRY

NO. 62326




2

MOUNT THE CROSSBAR AND MAKE WIRE CONNECTIONS

Expose the supply wire from the outlet box. Mount the crossbar to the junction box with the supplied screws

Gently pull the supply wires through the hole in the crossbar. Connect the black supply wire to the black fixture wire. Secure with the supplied wire nuts. Connect the white supply wires to the white fixture wire. Secure with the supplied wire nuts. Either wrap the green wire around one of the protruding screws or connect it to the supply ground wire. Secure all wire with electrical tape (not supplied). Tuck all wires carefully into the J-Box.




3

MOUNT FIXTURE TO THE CROSSBAR PLATE

Adjust the length of fixture by using grip lock.

Position the canopy over the crossbar plate.

Align the holes in the canopy and secure with the supplied thumb screws.



4

SECURE THE GLASS SHADES AND INSERT THE BULBS

Hold the glass shades at a slight angle to the fixture

and fit over the socket spring.

Do not insert shades vertically as the glass may crack.

Insert the supplied bulbs. MAXIMUM WATTAGE 40W.

DO NOT EXCEED THE WATTAGE AS STATED

ON THE WARNING LABEL AND IN THE INSTRUCTION

SHEETS

CERTIFICATION: UL DRY NO. 62326

