


LB Roman Tub Filler Trim (4-Hole)



Item	Part	Description
1	THP5191#CP	Escutcheon
2	THP4070	O-ring
3	THP5187#CP	Elbow Assembly
4	THP4229	Gasket
5	THP5185#CP	Diverter Bar
6	THP5214	Aerator
7	THP5429	Set Screw
8	THP5180	O-ring (1pc)
9	THP5190	Valve Connecor Assembly
10	THP5181	O-ring
11	THP5422	Set Screw
12	THP5430#CP	Handle Assembly (Cold)
13	THP5431#CP	Handle Assembly (Hot)